

Effective: 22/04/2026 to 23/04/2026

Display Action Officer: Yes

Officer: Gareth Scott (GASC)

Site: Peterston-Super-Ely (PA) (PA087)

Site: Peterston-Super-Ely (PA) (PA087)

Locality: PETERSTON SUPER ELY, VALE OF GLAMORGAN

Area: Peterston-Super-Ely

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,000.00	Asset - Locn.: 367817702 - MUGA			Feature Type: PL: MUGA			Area: Peterston-Super-Ely	
Batch: 81454384 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
81416887	1 bolt missing from goal area's	22/04/2026		PL: STRUCUTRE-Bolts Missing	Internal		Uncommitted	41501099
81416886	7 square caps missing from rear goal post uprights	22/04/2026		PL: STRUCTURE-Caps Missing	Internal		Committed	41501061
Asset: 1,000.01	Asset - Locn.: 37 - Infant Multi Unit			Feature Type: PL: Multi Unit			Area: Peterston-Super-Ely	
Batch: 81454385 - Inspection Batch	No actionable defects found			Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
Asset: 1,000.02	Asset - Locn.: 1393698040 - Rocking Horse			Feature Type: PL: Rocker			Area: Peterston-Super-Ely	
Batch: 81454386 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
81416888	Corrosion on legs	22/04/2026		PL: OTHER-Oth hazard (SPECIF	Internal		Committed	41500992
Asset: 1,000.03	Asset - Locn.: 1430487250 - Crazy Scrambler			Feature Type: PL: Rocker			Area: Peterston-Super-Ely	
Batch: 81454387 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
81416889	Slight rust present	22/04/2026		PL: STRUCUTRE-Rusty	Internal		Committed	41501056
Asset: 1,000.04	Asset - Locn.: -554291566 - Four seat Spring			Feature Type: PL: Rocker			Area: Peterston-Super-Ely	
Batch: 81454388 - Inspection Batch	No actionable defects found			Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
Asset: 1,000.05	Asset - Locn.: 167 - Bowl			Feature Type: PL: Rotator			Area: Peterston-Super-Ely	
Batch: 81454389 - Inspection Batch	No actionable defects found			Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
Asset: 1,000.06	Asset - Locn.: -701011090 - Supernova			Feature Type: PL: Rotator			Area: Peterston-Super-Ely	
Batch: 81454390 - Inspection Batch	No actionable defects found			Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
Asset: 1,000.07	Asset - Locn.: -681842543 - Slide / Tunnel			Feature Type: PL: Slide			Area: Peterston-Super-Ely	
Batch: 81454391 - Inspection Batch	No actionable defects found			Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
Asset: 1,000.08	Asset - Locn.: Combination Swing 2 Bay, 2 cradle, 1 basket			Feature Type: PL: Swing			Area: Peterston-Super-Ely	
Batch: 81454392 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
81416890	Both cradle seats starting to perish.	22/04/2026		PL: OTHER-Oth hazard (SPECIF	Internal		Committed	41501058
Asset: 1,000.09	Asset - Locn.: 1579714110 - Cantilever Swing			Feature Type: PL: Swing			Area: Peterston-Super-Ely	
Batch: 81454393 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
81416892	Bottom cap missing on top fitting	22/04/2026		PL: STRUCTURE-Caps Missing	Internal		Uncommitted	41501311
81416891	Slight wear in chains	22/04/2026		PL: SWING-Chains Worn	Internal		Committed	41500911
81416893	Bottom links wearing	22/04/2026		PL: SWING-Cruciform Link Worn	Internal		Uncommitted	41501379
Asset: 1,000.10	Asset - Locn.: -979289989 - Trim Trail			Feature Type: PL: Trim Trail			Area: Peterston-Super-Ely	
Batch: 81454394 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
81416894	1 post has slight play, monitor	22/04/2026		PL: OTHER-Oth hazard (SPECIF	Internal		Committed	41500642



Effective: 22/04/2026 to 23/04/2026

Officer: Gareth Scott (GASC)

Display Action Officer: Yes

Site: Peterston-Super-Ely (PA) (PA087)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,000.11	Asset - Locn.: -237755097 - Aerial Runway			Feature Type: PL: Zip Line			Area: Peterston-Super-Ely	
Batch: 81454395 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
81416895	Rubber casing on chain starting to perish, temporarily repair applied, monitor	22/04/2026		PL: OTHER-Oth hazard (SPECIF	Internal		Committed	41501431
Asset: 2,000.00	Asset - Locn.: 2048783312 - Site Surface			Feature Type: PL: Site Surfacing			Area: Peterston-Super-Ely	
Batch: 81454396 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
81416896	Slight moss on carpets, including on some units, could do with jetwashing	22/04/2026		PL: SURFACE-Contains Moss	Internal		Uncommitted	41500726
Asset: 3,000.00	Asset - Locn.: Site Bin			Feature Type: PL: Bin			Area: Peterston-Super-Ely	
Batch: 81454397 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
	No actionable defects found							
Asset: 3,000.01	Asset - Locn.: 164 - Fence			Feature Type: PL: Fencing			Area: Peterston-Super-Ely	
Batch: 81454398 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
81416897	Some rotten half round fence slats need replacing along the football field side	22/04/2026		PL: STRUCUTRE- Wood Rotten	Internal		Committed	41501380
Asset: 3,000.02	Asset - Locn.: 162 - Picnic Bench			Feature Type: PL: Picnic Table			Area: Peterston-Super-Ely	
Batch: 81454399 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
	No actionable defects found							
Asset: 3,000.03	Asset - Locn.: 1005018306 - Seats			Feature Type: PL: Seat			Area: Peterston-Super-Ely	
Batch: 81454400 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
	No actionable defects found							
Asset: 3,000.04	Asset - Locn.:			Feature Type: PL: Gate			Area: Peterston-Super-Ely	
Batch: 81454401 - Inspection Batch				Route: PL: Peterston-Super-Ely	Officer: Gareth Scott		Date: 22/04/2026	
81416898	X1 wooden gate close to football field closing to fast 3 seconds, should be between 5 - 8 seconds	22/04/2026		PL: GATE-Fails To Close	Internal		Committed	41501312

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00	Asset - Locn.: 367817702 - MUGA			Feature Type: PL: MUGA			Area: Peterston-Super-Ely	
41501061	7 square caps missing from rear posts goals (PL: STRUCTURE-Caps Missing)		Gareth Scott	Play: 1 Month	Monitored - OK	28/01/2025	28/02/2025	Est. PKSGRD/4085
41501099	2 bolts missing from goal area's (PL: STRUCUTRE-Bolts Missing)		Gareth Scott	Play: 6 Months	Monitored - OK	14/04/2025		
Asset: 1,000.02	Asset - Locn.: 1393698040 - Rocking Horse			Feature Type: PL: Rocker			Area: Peterston-Super-Ely	
41500992	Corrosion on legs (PL: OTHER-Oth hazard (SPECIFY))		Gareth Scott	Play: 1 Month	Monitored - OK	21/10/2024	21/11/2024	Est. PKSGRD/4078
Asset: 1,000.03	Asset - Locn.: 1430487250 - Crazy Scrambler			Feature Type: PL: Rocker			Area: Peterston-Super-Ely	
41501056	Slight rust present (PL: STRUCUTRE-Rusty)		Gareth Scott	Play: 1 Month	Monitored - OK	28/01/2025	28/02/2025	Est. PKSGRD/4084

f 3

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

0

—

—

—

—

1

—

—

5

—

—

7:54

Effective: 22/04/2026 to 23/04/2026

Officer: Gareth Scott (GASC)

Display Action Officer: Yes

Site: Peterston-Super-Ely (PA) (PA087)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.08	Asset - Locn.: Combination Swing 2 Bay, 2 cradle, 1 basket			Feature Type: PL: Swing		Area: Peterston-Super-Ely	
41501058	Cradle seats starting to perish (PL: OTHER-Oth hazard (SPECIFY))		Gareth Scott	Play: 1 Month	Monitored - OK	28/01/2025	28/02/2025	Est. PKSGRD/4084
41501310	Recommend fitting new grease nipples to the pear drops. (PL: OTHER-Oth hazard (SPECIFY))		Gareth Scott	Play: 1 Month	Job Committed	27/10/2025	27/11/2025	Est. PKSGRD/4109
	Asset: 1,000.09	Asset - Locn.: 1579714110 - Cantilever Swing			Feature Type: PL: Swing		Area: Peterston-Super-Ely	
41500911	Slight wear in chains, monitor (PL: SWING-Chains Worn)		Gareth Scott	Play: 1 Month	Monitored - OK	31/07/2024	31/08/2024	Est. PKSGRD/4070
41501311	Bottom cap missing (PL: STRUCTURE-Caps Missing)		Gareth Scott	Play: Parts Required	Job Created	27/10/2025		PKSGRD/4109
41501379	Bottom links wearing (PL: SWING-Cruciform Link Worn)		Gareth Scott	Play: 6 Months	Monitored - OK	19/01/2026		
	Asset: 1,000.10	Asset - Locn.: -979289989 - Trim Trail			Feature Type: PL: Trim Trail		Area: Peterston-Super-Ely	
41500642	1 post has slight play, monitor (PL: OTHER-Oth hazard (SPECIFY))		Gareth Scott	Play: 1 Month	Monitored - OK	16/10/2023	16/11/2023	Est. PKSGRD/4045
	Asset: 1,000.11	Asset - Locn.: -237755097 - Aerial Runway			Feature Type: PL: Zip Line		Area: Peterston-Super-Ely	
41501431	Rubber casing on chain starting to perish, temporarily repair applied, monitor (PL: OTHER-Oth hazard (SPECIFY))		Gareth Scott	Play: 1 Month	Job Committed	22/04/2026	22/05/2026	Est. PKSGRD/4121
	Asset: 2,000.00	Asset - Locn.: 2048783312 - Site Surface			Feature Type: PL: Site Surfacing		Area: Peterston-Super-Ely	
41500726	Slight moss on carpets, could do with jetwashing before the summer (PL: SURFACE-Contains Moss)		Gareth Scott	Play: 6 Months	Monitored - OK	15/01/2024		
	Asset: 3,000.01	Asset - Locn.: 164 - Fence			Feature Type: PL: Fencing		Area: Peterston-Super-Ely	
41501380	Some rotten half round fence slats, but secure at time of inspection. (PL: STRUCUTRE-Wood Rotten Mon)		Gareth Scott	Play: 1 Month	Job Committed	19/01/2026	19/02/2026	Est. PKSGRD/4116
	Asset: 3,000.04	Asset - Locn.:			Feature Type: PL: Gate		Area: Peterston-Super-Ely	
41501312	X2 wooden gates fail to close, new mechanisms have been installed (PL: GATE-Fails To Close)		Gareth Scott	Play: 1 Month	PL: Job Complete	27/10/2025	22/04/2026	Act. PKSGRD/4109

f 3

==

—

—

7

6

—

0

7

—

8

—

5

—

—

—

4

—

8

—

7:54